

Network Video Recorder

Version: V4.20.002 build210705

Release Note

(2021-07-29 **Internal**)

Firmware Basic Information	Firmware Version	V4.20.002 build210705
	Play Library	7.3.3.0
	Web component	V4.0.1 build 210603
	Plugin	V3.0.6.46
	ONVIF	V2.2
	ISAPI	V2.0
	Kernel	K51&K52: V2.2.0 build 210623 KY2017: V2.2.0 build 210607 K72A:V2.2.0 build 210609

New Feature

Rebuild All Data in Webpage

This new firmware add a new feature that support repairing database in webpage, you can repair the database remotely now.

Live View

Playback

Picture

Configuration

HDD Management

Net HDD

HDD Detection

Cloud Storage

HDD Management

Set

Format

Rebuild All...

☒	HDD No.	Capacity		Free space	Status	Type	Property	Progress
☒	3	3726.02GB	Normal	1321.00GB	Normal	Local	R/W	

Upgrade Feature

Upgrade database mechanism

Upgrade database mechanism, optimize recording retrieval speed and stability.

Related product list:

Please check the firmware mapping table to check the products this version supports.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.